


First the Speedometer quit working, then about a year later the Odometer quit  
Then I started looking at fixing SP/OD problems first I replaced the VSS  
Then I checked and reran wiring  
(Squirrels ate wrapping from and some of the wiring, they love fusible links)  
Removed SP/OD gage  
Noticed 20 tooth OD gear had only 19 teeth



Ordered a 20 tooth replacement  
Then I noticed that the circuit board on left for the speedometer part was fried  
Of course I noticed this after I order parts .....



This is where the 2 wires from board go to the speedometer section of the gage both the Speedometer and Odometer are in same gage. But they are two different things and both

run off the VSS so if one works then your VSS should be ok ..If Odometer quits then it is MOST LIKELY just the gear. That can be replaced easily. Well kind of  
If the speedometer quits and odometer still works then you COULD have same problem I have.

I am now looking at how to replace circuit board and so far I am at a loss  
Any ideas or help .. should I just look at replacing the whole SP/OD as a unit??